

## Appendix E (i) Summary of additional feedback received

Source	Theme	Comments received
Local residents Uley. 4 emails and 1 letter: objections 1 objection from tenant impacted  These residents have objected or complained/commented about the redevelopment at the Knoll.	Highway Safety:	<ul style="list-style-type: none"> <li>• School, café and Prema Arts Centre leads to congestion on South Street</li> <li>• Limited on-street parking.</li> <li>• Danger to school children walking/cycling</li> <li>• Blind bend</li> <li>• Lack of pavement</li> </ul>
	Unsuitable location	<ul style="list-style-type: none"> <li>• Linked to highway safety concerns , setting of the site, impact of development</li> <li>• Other places abandoned, empty and unused in the village</li> </ul>
	Residents and tenants forced to move	<ul style="list-style-type: none"> <li>• Emotional distress to residents</li> <li>• Residents won't be re housed in the village</li> </ul>
	Lack of maintenance of Swedish houses has led to the need to demolish	<ul style="list-style-type: none"> <li>• Deliberately neglected</li> <li>• In good repair</li> <li>• Regular repairs stopped</li> <li>• Some 'abused' by tenants</li> <li>• Reasons for redevelopment 'unfounded'</li> </ul>
	Energy Efficiency/Environmental concerns	<ul style="list-style-type: none"> <li>• Swedish Timber are solid in construction and warm</li> <li>• EPC 'C', with some internal insulation</li> <li>• Can the Council achieve an EPC 'A' rating?</li> <li>• Potential loss of trees/ wildlife habitat</li> <li>• Potential drainage problems</li> </ul>
	Heritage value of the Swedish Timber Houses	<ul style="list-style-type: none"> <li>• Gifted by Sweden</li> <li>• Historical interest</li> <li>• Could be repaired</li> <li>• Valued by the community</li> </ul>
	Support	<ul style="list-style-type: none"> <li>• Need for affordable housing recognised/supported but not in this location</li> </ul>